## SPRINGFIELD TECHNICAL COMMUNITY COLLEGE

## **ACADEMIC AFFAIRS**

Course Number:	MECH-438	Department:	Mechanical Eng. Technology			
Course Title:	CAM II	Semester:	Spring	Year:	2009	

## **Objectives/Competencies**

Course Objective	Competencies		
1. Create lathe operation setups using CAD solid modeling.	<ul> <li>Create proper file folders for lab projects.</li> <li>Recognize proper chuck to use for part.</li> <li>Insert all components of lathe setup in an assembly.</li> <li>Edit stock to required length.</li> <li>Constrain stock and part in lathe chuck.</li> </ul>		
2. Open lathe setups in CAM and perform manufacturing operations.	<ul> <li>Transform assembly into proper plane for lathe operations.</li> <li>Ensure part is at proper X, Y, Z origin</li> <li>Identify stock and fixture solids for manufacturing.</li> <li>In addition to MECH-337, CAM 1, Objective 10:</li> <li>Perform Back Turning operations.</li> <li>Adjust process planning for tolerance control.</li> </ul>		
3. Create multiple mill operation setups using CAD solid modeling.	<ul> <li>Create proper file folders for lab projects.</li> <li>Decide how many operations will be required for part manufacture.</li> <li>Discuss how the result of one operation becomes the stock in the next.</li> <li>Insert Kurt Vise components into CAD system.</li> <li>Create initial stock as a solid.</li> <li>Discuss and use fixtures in CAD assemblies.</li> </ul>		

CAMII	
Course Number: MECH-438	

<ul> <li>Constrain stock, fixture (when needed), and part in Kurt Vise.</li> <li>Include necessary fasteners when needed.</li> </ul>	<ul> <li>Transform assembly into proper plane for mill operations.</li> <li>Ensure part is at proper X, Y, Z origin</li> <li>Identify stock and fixture solids for manufacturing.</li> </ul>	<ul> <li>In addition to MECH-337, CAM 1, Objectives 5 and 9:</li> <li>Recognize variable Z-level parts.</li> <li>Identify surface features.</li> <li>Perform machining using a ball mill.</li> <li>Adjust process planning for tolerance control.</li> </ul>	<ul> <li>Recognize parts requiring a multi-axis mill.</li> <li>Insert 4<sup>th</sup> Axis Vise components into CAD system.</li> <li>Define part volumetric center.</li> <li>Create initial stock as a solid.</li> <li>Constrain stock and part in 4<sup>th</sup> Axis Vise.</li> <li>Perform indexing operations.</li> </ul>
	4. Open mill setups in CAM and perform manufacturing operations.		5. Perform 4-axis machining.